



DEPARTMENT OF
WATER RESOURCES

Fact Sheet **BUTTE CREEK Site 14.0**

Critical Levee Erosion Site

Emergency Levee Repairs

Location

River: Butte Creek

River Mile: 14.0

Latitude/Longitude:

39.685634/-121.778801

Nearest Impact Area: Durham

County: Butte

Bank: Right

Type of Damage

Bank erosion

Length of Repair


1,000 feet (approximate)

Repair Type

Rock slope protection

Lead Agency

Department of Water Resources



**For further information,
please contact:**

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov